

One Way Check Valves has metal to metal seals and spring set In order to prevent jamming of Stab in Receptacle the threads Change of Valves is NOT recommended to be done Offshore